

Date: Tuesday, 11/6/2007 1:25:07 PM
 User: Kim Johnston

Process Sheet

50

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : LONG STEP ASSEMBLY HIGH SKID RH
Job Number : 35552	
Estimate Number : 10274	
P.O. Number : <i>N/A</i>	Part Number : D350591312
This Issue : 11/6/2007 S.O. No. : <i>N/A</i>	Drawing Number : D3272 REV B
Prsht Rev. : NC	Project Number : N/A
First Issue : 11/6/2007 Type : LARGE FAB ASSY	Drawing Revision : B
Previous Run : 35195	Material : <i>N/A</i>
Written By : <i>[Signature]</i>	Due Date : 12/10/2007 Qty: 10 Um: Each
Checked & Approved By : <i>[Signature]</i>	
Comment : Est Rev: A 04.03.22 New issue KJ/RF	
Est Rev: B 07-06-09 Added D3572-1 JLM	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-312 CHG001

KS 07-11-26

2.0	D32721	STEP
-----	--------	------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

STEP

BATCH: *335592**KS 07-11-20*

3.0	D30671	End Plate
-----	--------	-----------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate *335079**KS 07-11-20*

4.0	D32191	Support
-----	--------	---------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3219-1 Support *335591**KS 07-11-20*

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 11/6/2007 1:25:07 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M105058

3-Grind End Plate flush

See 07-11-20 10
See 07-11-20 10
SAD 07-11-22 (10)

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

AD 07-11-22 (10)

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

6 07-11-22 (10)

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

SAD 07-11-22 (10)

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

See 07-11-22 10

10.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3065-041

Step Leg Assy

333510

See 07-11-22 10

11.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

2 D3066-1

Spacer

334447 = 6
335692 = 14

See 07-11-22 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 MS20600AD4W4

Rivet

1105953 = 160*1107.11.26 10*

13.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble Leg Assembly as per Dwg D3272.

1107.11.26 10

14.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

1107.11.26 10

15.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3067-1

End Plate

335079*1107.11.26 10*

16.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod 1105058

4-Grind End Plate flush

a.m 07.11.27 10

5-Install last rivet.

*a.m 07.11.27 10**1107.11.26 10**1107.11.26 10**1107.11.26 10*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 11/6/2007 1:25:07 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PD 07-11-27 (10)

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/11/27 (10)

19.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch up Alodine

M-1

07/11/27

10X RH

20.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M105914

M-1

07/11/28

40 RH

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3272 and QSI 005 4.4

M106030

YD

07-11-28

10 RH

22.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

07/11/30 (10)

23.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

24.0

D22303

Mounting Lug



Comment: Qty.: 4.0000 Each(s)/Unit Total: 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2230-3 Mounting Lug

B35470

AS 07/12/05

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 11/6/2007 1:25:07 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

25.0

D2618

Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2618

Bushing

35096

AS 07/12/05

(X10)

26.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 6.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2856-400-720 Abrasion Strip

B34642

AS 07/12/05

(X10)

27.0

D32351

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D3235-1

Mounting Lug

B33249

AS 07/12/05

(X10)

28.0

D3278041

Support Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D3278-041 Support Assembly

B34951

AS 07/12/05

(X10)

29.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

M105408

AS 07/12/05

(X10)

30.0

AN413A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN4-13A

Bolt

M106043

AS 07/12/05

(X10)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 11/6/2007 1:25:07 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

31.0

AN536A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN5-36A

Bolt

M105953

AS 07/12/05

(X10)

32.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

M105792

AS 07/12/05

(X10)

33.0

AN960JD416

Washer



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 AN960JD416

Washer

M105900

AS 07/12/05

(X10)

34.0

AN960JD516

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD516

Washer

M104156

AS 07/12/05

(X10)

35.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or -3)

M105558

AS 07/12/05

(X10)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: LD Date: 01/21/07
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 11/6/2007 1:25:07 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 35552

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

36.0

MS21042L4

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 MS21042L4

Nut (or -4)

M105054

AS 04/12/05

(X10)

37.0

MS21042L5

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L5

Nut (or -5)

M105430

AS 04/12/05

(X10)

38.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

12-06 (10)

39.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-312

Location:

15 7/12/06

SO (10X)

40.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

12/07/07 (10)

Job Completion



12/07/07

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART

DESIGN <i>qp</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED07.06.04 *[Signature]*

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *35552*

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN	APPROVED	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	CE	APPROVED	DRAWING NO. D3272
DATE	07.05.18	TITLE	STEP ASSEMBLY, HI LONG
		SCALE	1:20
		SHEET 2 OF 3	REV. B



D3272-041 STEP ASSEMBLY (LH. SHOWN)
D3272-042 STEP ASSEMBLY (RH, OPPOSITE)



RELEASED
07.06.04


WORK ORDER
NO. 35022
CONTROLLED COPY
EFFECT TO AMENDMENT
WITHOUT NOTICE
D3272-041
D3272-042
D3272-043
D3272-044
D3272-045
D3272-046
D3272-047
D3272-048
D3272-049
D3272-050
D3272-051
D3272-052
D3272-053
D3272-054
D3272-055
D3272-056
D3272-057
D3272-058
D3272-059
D3272-060
D3272-061
D3272-062
D3272-063
D3272-064
D3272-065
D3272-066
D3272-067
D3272-068
D3272-069
D3272-070
D3272-071
D3272-072
D3272-073
D3272-074
D3272-075
D3272-076
D3272-077
D3272-078
D3272-079
D3272-080
D3272-081
D3272-082
D3272-083
D3272-084
D3272-085
D3272-086
D3272-087
D3272-088
D3272-089
D3272-090
D3272-091
D3272-092
D3272-093
D3272-094
D3272-095
D3272-096
D3272-097
D3272-098
D3272-099
D3272-100



DESIGN <i>GP</i>	DRAWN BY <i>JB</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20

RELEASED


07.06.04 *[Signature]*



DETAIL C

B D3272-1 STEP

(MAKE FROM D2622-120 STEP EXTRUSION)



DETAIL C
(SCALE 1:5)

DRILL $\phi 0.128$ (#30) FROM JIG ON
BOTH SIDES OF D3272-1 EXTRUSION
TO MATCH D3065-041 HOLE PATTERN

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 35552

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.